

Brussels, 7 March 2012

**VIGIL INFORMATION BULLETIN: VIGIL LCD Software version 2.20**

**IDENTIFICATION:**

All Vigil LCD's with LCD software version 2.20 mounted on Vigil serial numbers 23.350 – 24.970.

The LCD software version can be located during the startup sequence, in the INFO menu.

**ORIGIN:**

An interruption can occur on Vigils with LCD software version 2.20, resulting in a freezing or locking of the LCD screen.

**ACTION:**

Replacing the LCD at the next reserve repack cycle is advised.

If your LCD controller freezes, it should be replaced before the next jump.

**LOGISTIC:**

If your Vigil is affected by this notice, please contact your dealer or [service@vigil.aero](mailto:service@vigil.aero), or [candace@vigil.aero](mailto:candace@vigil.aero) (for USA, Canada and South America) with the serial number of your Vigil.

We will verify if your unit needs to be changed, and will send a free replacement LCD if needed.

**REMARKS:**

This issue can occur prior to the self-test and in this case, the unit is not switched on.

In some cases, this can occur immediately after landing.

If your 2.20 LCD controller has already been replaced, this information bulletin does not apply to you.